



## Alpha Miner/Vnish Antminer L7, S19, T19, S21 T21 ASIC Families. FW v.1.2.6 RC4 - Change Log

### 🚩 New Features:

- Added support for Antminer S21 Hydro model HHB68601

### 🟡 Improvements:

- Enhanced miner stability across the board
- Implemented various UI/UX enhancements for better user experience

### 🐛 Bug Fixes:

- Resolved an issue where fans were incorrectly marked as lost during initialization if the minimum fan speed was set to 0%.
- Corrected sensor functionality during the resume process on Antminer L7.
- Fixed autotuning issues for Antminer S21, S21 Pro, S21 XP Immersion, S21 Immersion, S21 XP, S21 Hydro, S21 XP Hydro, T21, S19k Pro, S19 XP, S19j XP, S19 XP Hydro, S19e XP Hydro, and T19 Pro Hydro.
- Addressed incorrect chip hashrate display following frequency downgrades
- Fixed errors related to disabling profiles
- Resolved an issue where the top preset could appear lower than the current preset

📍 30 N. Gould Street, Ste. 7253, Sheridan, WY 82801, USA

🚩 [alphaminer.io](https://alphaminer.io)

